



TOOLS NEEDED

- 5/16" Wrench / Nut Driver
- 3/8" Wrench
- 5/32" Allen head wrench
- 1/8" Allen head wrench
- Small pliers or vise grips
- Lock-Tite

1. Remove the screws from the front access cover.
2. Remove the 2 screws holding the pinch cable bracket.
3. Remove the 2 screws holding the cable connection bracket.
4. Remove the screws connecting the door brackets to slide rail.
(Remove doors and set aside)
5. Remove old door guides (Part#1017) and replace with new ones.
6. Replace doors in reverse order they were removed.

NOTE: THIS DRAWING EMBODIES A CONFIDENTIAL PROPRIETARY DESIGN ORIGINATED AND OWED BY QUIKSERV CORP., AND IS SUBMITTED UNDER A CONFIDENTIAL RELATIONSHIP. ALL PATENT, MANUFACTURING, SALE RIGHTS REGARDING THE SAME ARE RESERVED EXCEPT TO THE EXTENT RIGHTS ARE EXPRESSLY GRANTED TO OTHERS. THE RECIPIENT AGREES BY ACCEPTING THESE DRAWINGS NOT TO SUPPLY OR DISCLOSE ANY INFORMATION REGARDING THEM TO ANY UNAUTHORIZED PERSON.

Quikserv Corp.
 www.quikserv.com
 1-800-388-8307

BI-PARTING-SC DOOR GUIDE REPLACEMENT

Submitted By:
 Brian Coble

DATE:
 12/5/2014

Sheet:
 BP-SC-DG